

1 Purpose

This document describes new functions, the changes, improvements and fixed bugs and problems in the following firmware version:

- 57.1007.0009
- in comparison with the firmware version:
- 57.1007.0008 (first released version)

2 New functions

The following new functions have been integrated:

- none

3 Improvements

The following improvements were made:

- Push rod: improved maximum stroke by changing the distance between reference position and basic position.
- Remote control: The external commands and the acknowledgements of the instrument are terminated with the control character **CR LF**.

4 Fixed bugs and problems

The following bugs and problems were fixed:

- Restoring the system database: After a system restore, the instrument was not immediately restarted.

5 Known bugs and problems

The following bugs or problems are known:

- none